

LOCAL NOTICE

TO MARINERS

U.S. Department
of Transportation

United States
Coast Guard

WEEKLY SUPPLEMENT

ISSUED BY: COMMANDER ELEVENTH COAST GUARD DISTRICT (POW)

,Coast Guard Island, Building 50-6, Alameda, California 94501-5100

Telephone: Day: (510) 437-2976 24 Hour FAX: (510) 437-5836

For subscription information and other questions, comments and suggestions call (510) 437-2976.

Boating Safety Classes or Information: 1-800-869-SAIL (7245)

**** Electronic Bulletin Board Service: (703) 313-5910 ****

300 to 28.8 bps, 8 data bits, no parity, 1 stop bit

**** NIS watchstander, 24 hours a day at (703) 313-5900 ****

**** INTERNET ADDRESS ****

HTTP://www.navcen.uscg.mil

OR

FTP://ftp.navcen.uscg.mil

BROADCAST NOTICE TO MARINERS - Significant information concerning aids to navigation and waterways management

promulgated by BNM 0374/97 to BNM 0400/97 has been incorporated in this notice.

LIGHT LIST REFERENCE: COMDTPUB P16502.6 LIGHT LIST, VOLUME VI 1996 Edition

USE OF THE LOCAL NOTICE TO MARINERS

With the exception of Sections II and III, the Weekly Supplemental editions contain only new information available in the past seven days. For all available information concerning the waterways of the Eleventh Coast Guard District, consult Monthly Edition 19/97.

I. SPECIAL NOTICES

OMEGA STATUS AS OF 13 MAY 1997

All Omega Stations are on-air.

Omega status recording : Phone number (703) 313-5906.

LNМ 20/97 dated 13 May 1997.

LORAN-C STATUS AS OF 13 MAY 1997

Loran-C Stations for 8290/9940 Chains are on air.

For information regarding the Loran-C System, contact the Coordinator of Chain Operations West Coast at (707)765-7590.

LNM 20/97 dated 13 May 1997.

D-GPS STATUS AS OF 13 MAY 1997

All dGPS sites are on air.

For information regarding the dGPS system, or for status updates contact the Petaluma Control Center at (707)765-7612/7613.

LNM 20/97 dated 13 May 1997.

II. DISCREPANCIES / DISCREPANCIES CORRECTED

DISCREPANCIES: (bold type and * denote new information since last LNM) CHARTS BNM
LNM

LLNR	NAME OF AID	STATUS	AFFECTED	REF.	REF.
5.00	POINT LOMA LIGHT	REDUCED INTENSITY/OBSCURED	18740	1043-95	
46/95					
135.00	LOS ANGELES LIGHT	BURNING DIM	18740	N/A	20/97*
177.00	NOAA ENVIRONMENTAL LB EB 46045	EXTINGUISHED	18740	0198-97	
10/97					
510.00	NOAA ENVIRONMENTAL LB EB 46006	MISSING/EXTINGUISHED	18620	N/A	
20/97*					
1605.00	SHELTER ISLAND YACHT BASIN BUOY 7	OFF STATION	18773	0243-97	
13/97					
3290.00	CABRILLO BEACH LAUNCH RAMP NORTH LT	EXTINGUISHED	18751	0696-96	
96 39/96					
4275.00	HORSESHOE BAY E BREAKWATER LT	EXTINGUISHED	18649	N/A	
15/97					
4302.00	SAN FRANCISCO WEST YACHT HBR LB 3	MISSING	18649	N/A	
06/97					
4780.00	BALLENA BAY LIGHT 1	IMPROPER CHARACTERISITIC	18649	0285-97	
16/97					
5790.00	MOLATE POINT WHARF SOUTH END LT	EXTINGUISHED/FOG SIGNAL INOP	18649		
0007-97	02/97				
6280.00	AMORCO WHARF LIGHTS (2)	EXTINGUISHED	18656	0344-97	
18/97					
7240.00	SACRAMENTO RIVER DWSC LT 16	EXTINGUISHED	18661	0251-97	
14/97					
7555.00	SACRAMENTO RIVER DWSC LT 74	EXTINGUISHED	18662	0255-97	
14/97					
7920.00	BODEGA BAY DAYBEACON 29	DAMAGED	18643	0286-97	
17/97					
8420.00	LAKE TAHOE BUOY 6	OFF STATION	18665	N/A	15/97
8445.00	LAKE TAHOE BUOY 16	MISSING	18665	N/A	15/97
8450.00	LAKE TAHOE BUOY 18	MISSING	18665	N/A	16/97
8500.00	LAKE TAHOE BUOY 32	MISSING	18665	N/A	15/97
8515.00	LAKE TAHOE BUOY 38	MISSING	18665	N/A	15/97
8520.00	LAKE TAHOE BUOY 40	MISSING	18665	N/A	15/97

DISCREPANCIES CORRECTED:

2235.00	CHULA VISTA CHANNEL DAYBEACON 17	WATCHING PROPERLY	18773	
N/A 15/97				
2800.00	ANAHEIM WEST JETTY LIGHT 5	WATCHING PROPERLY	18749	0341-97
18/97				
2805.00	ANAHEIM EAST JETTY LIGHT 6	WATCHING PROPERLY	18749	0341-97
18/97				
2830.00	ALAMITOS BAY EAST JETTY LIGHT 2	WATCHING PROPERLY	18749	0341-97
18/97				
2835.00	ALAMITOS BAY WEST JETTY LIGHT 1	WATCHING PROPERLY	18749	0341-97
18/97				

III. TEMPORARY CHANGES/TEMPORARY CHANGES CORRECTED - ESTABLISHED/DISCONTINUED AIDS

TEMPORARY CHANGES: (bold type and * denote new information since last LNM) CHARTS

LLNR	NAME OF AID	STATUS	AFFECTED	REF.	REF.
0.00	SAUSALITO CHANNEL LIGHTED BUOY WR1	TEMPORARILY ESTABLISHED		18649	
0798-96	43/96				
2054.00	SWEETWATER CHANNEL LIGHT 4	TRLB	18773	N/A	20/97*
2056.00	SWEETWATER CHANNEL LIGHT 6	TRLB	18773	N/A	20/97*
2470.00	NEWPORT BAY CHANNEL LIGHT 11	TRLB	18754	0597-95	24/95
3221.00	RESERVATION POINT NORTH BUOY	TEMPORARILY DISCONTINUED		18751	
N/A	29/96				
3222.00	RESERVATION POINT MIDDLE BUOY	TEMPORARILY DISCONTINUED		18751	
N/A	29/96				
3223.00	RESERVATION POINT SOUTH BUOY	TEMPORARILY DISCONTINUED		18751	
N/A	29/96				
4606.00	OAKLAND HBR BAR CHAN LB 2	TEMPORARILY RELOCATED	18649	1154-95	50/95
4630.00	OAKLAND OUTER HARBOR LIGHTED BUOY 1B	TEMPORARILY RELOCATED			
18649	0235-96	38/95			
4645.00	OAKLAND OUTER HARBOR LIGHTED BUOY 3	TEMPORARILY RELOCATED		18649	
1229-95	38/95				
4650.00	OAKLAND OUTER HARBOR LIGHTED BUOY 5	TEMPORARILY RELOCATED		18649	
1229-95	38/95				
8035.00	TOMALES BAY BUOY 3	TRUB	18643	0247-97	14/97

TEMPORARY CHANGES CORRECTED:

2800.00	ANAHEIM WEST JETTY LIGHT 5	FOG SIGNAL REESTABLISHED	18749	0341-97
18/97				
2835.00	ALAMITOS BAY WEST JETTY LIGHT 1	FOG SIGNAL REESTABLISHED	18749	
0341-97	18/97			

IV. CHART CORRECTIONS (See LNM 19/97 for explanation of format.)

18643	16 th ed., 12/16/95 LAST LNM 18/96 NAD 83	(NOS Silver Spring)
	20/97	
	CA - Bodega and Tomales Bays	
	Add Channel Tabulation from Enclosure (1).	
18645	22 nd ed., 04/04/92 LAST LNM 17/95 NAD 83	(NOS Silver Spring)
	20/97	
	CA - Gulf of the Farallons	
	Change Note H to:	

NOTE H

MAIN SHIP CHANNEL SAN FRANCISCO ENTRANCE

Depths entering from seaward,
surveys to NOV 1996

Left outside quarter.....52.0ft
Left inside quarter.....53.0ft
Right inside quarter.....53.3ft
Right outside quarter.....51.7ft
37°42'30.0"N 122°27'00.0"W

18649 58th ed., 02/03/96 LAST LNM 11/97 NAD 83 (NOS Silver Spring)
20/97

CA - Entrance to San Francisco Bay
Add Channel Tabulation from Enclosure (2).

18749 34th ed., 11/16/96 LAST LNM 16/97 NAD 83 (CGD11) 20/97
CA - San Pedro Bay

Add Lighted Mooring Buoy GCO1, FI W Priv "GCO-1" 33°45'19.0"N
118°10'00.0"W
Lighted Mooring Buoy GCO2, FI W Priv "GCO-2" 33°45'19.0"N
118°09'38.0"W
Long Beach Pier J North Breakwater, joining: 33°44'21.4"N
118°11'11.0"W
33°44'24.3"N 118°10'59.7"W
33°44'23.6"N 118°10'58.2"W
33°44'17.9"N 118°10'56.1"W

Long Beach Pier J South Breakwater, joining: 33°44'05.4"N 118°11'07.3"W

33°44'05.4"N 118°10'56.6"W
33°44'06.4"N 118°10'55.4"W
33°44'11.3"N 118°10'55.4"W
Long Beach Pier J Light 3, FI G 2.5s, 25ft, 5M, "3" 33°44'11.2"N
118°10'55.4"W
Long Beach Pier J Light 4, FI R 2.5s, 25ft, 5M, "4" 33°44'18.1"N
118°10'56.2"W

Delete Anaheim Bay Navy Mooring Buoy 2 33°43'45.0"N
118°05'49.5"W
Anaheim Bay Navy Mooring Buoy 3 33°43'49.5"N
118°05'45.5"W
Anaheim Bay Navy Mooring Buoy 7 33°43'49.0"N
118°05'58.0"W
Anaheim Bay Navy Mooring Buoy 1A 33°44'02.0"N
118°05'30.5"W
Anaheim Bay Navy Mooring Buoy 2A 33°44'01.5"N
118°05'29.0"W
Anaheim Bay Navy Mooring Buoy 3A 33°43'58.5"N
118°05'23.5"W
Anaheim Bay Navy Mooring Buoy 4A 33°44'00.0"N
118°05'23.0"W

18751 37th ed., 11/16/96 LAST LNM 17/97 NAD 83 (CGD11) 20/97
CA - Los Angeles and Long Beach Harbors

Add	Lighted Mooring Buoy CGO1, FI W Priv "GCO-1"	33°45'19.0"N
118°10'00.0"W		
	Lighted Mooring Buoy GCO2, FI W Priv "GCO-2"	33°45'19.0"N
118°09'38.0"W		
	Long Beach Pier J North Breakwater, joining:	33°44'21.4"N
118°11'11.0"W		
	33°44'24.3"N 118°10'59.7"W	
	33°44'23.6"N 118°10'58.2"W	
	33°44'17.9"N 118°10'56.1"W	
Long Beach Pier J South Breakwater, joining:		33°44'05.4"N 118°11'07.3"W
	33°44'05.4"N 118°10'56.6"W	
	33°44'06.4"N 118°10'55.4"W	
	33°44'11.3"N 118°10'55.4"W	
	Long Beach Pier J Light 3, FI G 2.5s, 25ft, 5M, "3"	33°44'11.2"N
118°10'55.4"W		
	Long Beach Pier J Light 4, FI R 2.5s, 25ft, 5M, "4"	33°44'18.1"N
118°10'56.2"W		

V. ADVANCE NOTICE OF CHANGES IN AIDS TO NAVIGATION

SOUTHERN CALIFORNIA - LOS ANGELES HARBOR - AID ESTABLISHMENT - The U.S. Coast Guard will establish a range in Los Angeles Main Channel in May 1997. The range will mark the centerline of the realigned channel due to the Pier 400 dredging and landfill project. The Front Light will be established in position 33°43'09.6"N, 118°16'17.1"W with a fixed yellow light. The Rear Light will be established in position 33°43'10.9"N, 118°16'20.0"W with a 6 second isophase yellow light. Comments may be directed to Commander (Pow), Coast Guard Island, Bldg. 50-6, Alameda CA 94501-5100, Attn: LCDR Anne Burkhardt, or call (510)437-2978.

Charts: 18749, 18751 LNM 10/97 dated 04 March 1997

VI. PROPOSED CHANGES IN AIDS TO NAVIGATION

None.

VII. GENERAL INFORMATION

None.

BRIDGE INFORMATION - DISCREPANCIES AND CORRECTIONS -

Questions regarding bridge operations, regulations, or permit applications, please contact: Eleventh Coast Guard District Bridge Section, Coast Guard Island, Building 50-6, Alameda, CA 94501-5100 Phone: (510) 437-3514.

NORTHERN CALIFORNIA - SAN FRANCISCO BAY - DUMBARTON RAILROAD BRIDGE. The navigation lights have been relighted.

Chart: 18651

NORTHERN CALIFORNIA - SAN FRANCISCO BAY - SAN MATEO-HAYWARD FIXED BRIDGE. CalTrans has completed seismic test boring at the bridge. All marine construction equipment has been removed.

Charts 18651, 18652

NORTHERN CALIFORNIA - SACRAMENTO RIVER - "I" STREET BRIDGE - Removal of logs and other debris north of the bridge is in progress. Clearance operations are scheduled to be completed by 26 May 1997.

Chart: 18662

NORTHERN CALIFORNIA - HUMBOLDT BAY - EUREKA SLOUGH - U.S. 101 BRIDGE. CalTrans is painting the bridge. Vertical clearance under the bridge is reduced by approximately 7 feet. A barge will also reduce the horizontal clearance by approximately 20 feet during the daytime. Work should conclude by approximately 01 June 1997.

Chart: 18622

VIII. CORRECTIONS TO LIGHT LIST, VOLUME VI; PACIFIC COAST AND PACIFIC ISLANDS 1996:

(* Denotes the column in which a correction has been made or new information added.)

(1) No. Remarks	(2) Name and location	(3)	(4)	(5) Position	(6)	(7) Characteristic	(8) Height	Range	Structure
CALIFORNIA - Eleventh District									

N/W

Long Beach Harbor

aid.	2875 (18/97)	- General Construction	33 45.3 FI W			White with blue stripe.	Private
	*	Lighted Mooring Buoy 1	118 10.0	*		*	*
*							
aid.	2880 (18/97)	- General Construction	33 45.3 FI W			White with blue stripe.	Private
	*	Lighted Mooring Buoy 2	118 09.6	*		*	*
*							
	3008 (18/97)	- PIER J LIGHT 3	33 44.2 FI G 2.5s	25	5	SG on pole.	
	118 10.9			*	*	*	*
*							
	3009	- PIER J LIGHT 4	33 44.3 FI R 2.5s	25	5	TR on pole. (18/97)	

118 10.9

*		*	*	*	*	*	*
*							

IX. ADDITIONAL ENCLOSURES

Enclosure (1)- Channel Tabulation for Chart 18643

Enclosure (2)- Channel Tabulation for Chart 18649

H. H. SHARPE

Chief, Aids to Navigation and
Waterways Management Branch
Eleventh Coast Guard District
Enclosure (1)

Enclosure (2)